



How to Care for Super Matte 3DL (Thermofoil) Products

Super Matte 3DL (thermofoil) has a top coat that gives it a soft “peach fuzz” texture. As with any material, smoke, oils, grease and sunlight will wear and discolor thermofoil. Fortunately, keeping Super Matte thermofoil parts clean and looking new is very easily done.

Everyday spills and splatters can be cleaned with warm water and a soft cloth. Harsh chemicals and cleansers such as acetone and lacquer thinners will remove the Super Matte finish resulting in a shiny, uneven, surface that is permanently damaged.

JBC will not warranty Super Matte parts that have been improperly cleaned.

